



ecology and environment, inc.

223 WEST JACKSON BLVD., CHICAGO, ILLINOIS 60606, TEL. 312-663-9415

International Specialists in the Environmental Sciences	International	Specialists	in the	Environmental	Sciences
---	---------------	-------------	--------	---------------	----------

DATE:

March 10, 1983

TO:

File/USEPA Region V

FROM:

Don Mueller/Anne C. Sause

SUBJECT:

Preliminary Assessment

Michigan/TDD#R5-8212-03A-263

Saline/Hoover Universal Saline Die Cast Division

MID980795512

Attached is EPA's Preliminary Assessment Form 2070-12 for the above referenced site.

Primary information was gathered from the following source(s):

- 1. Ecology and Environment FIT files, Region V-Chicago
- 2. Michigan Department of Natural Resources, Lansing (Water reports and water records)

Information indicates the following responsible parties should be listed. They are listed here because of space limitations:

- 1.
- 2.
- 3.

Presently, data gaps or no verification exists in the following key area(s):

- 1. Waste quantity
- 2.
- 3.

A review of the available data indicates that additional information will be necessary to assess the impact(s) on:

- 1 Groundwater contamination extent
- 2 Surface water contamination extent
- 3.
- 4.
- 5.

Suggested methods/sources for obtaining additional information are:

- 1. Groundwater monitoring low priority since population
- 2. effected is less than 195
- 3.

Notice of an apparent need for emergency action was transmitted to $_{\rm N/A}$ on $_{\rm N/A}$

_		-
 	al a	

8/11

SEPA

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT PART 1 - SITE INFORMATION AND ASSESSMENT

I. IDENTIFICATION					
DI STATE	02 SITE NUMBER				
MI	D980795512				

PART 1 - SITE INFORMA	TION AND ASSESSMENT MID 10980795512				
II. SITE NAME AND LOCATION					
01 SITE NAME (Legal, common, or descriptive name of site)	02 STREET, ROUTE NO., OR SPECIFIC LOCATION IDENTIFIER				
Hoover Universal Saline Die Cast Division	232 Monroe Street DASTATE TOS ZIP CODE TOB COUNTY TO				
Saline	Mi 48176 Washtenaw 1612				
09 COORDINATES LATITUDE LONGITUDE 4 2° 0 9′ 3 8 . 1″ 0 8 3° 4 6′ 0 3 . 3″	Saline Quad, T45 R5E Section 1				
From US Route 12: northeast into Saline. Ex	it on Monroe (Macon) Street South and				
follow to site (232 Monroe Street).					
III. RESPONSIBLE PARTIES					
01 OWNER (M. KNOWN)	02 STREET (Business, malling residential)				
Hoover Universal	135 East Rennett				
03 CITY	04 STATE 05 ZIP CODE 06 TELEPHONE NUMBER				
Saline	Mi 48176 (313)429-2552				
07 OPERATOR (Il known and different from owner)	OB STREET (Business, melling, residential)				
Hoover Ball and Bearing Company	same as owner				
109 Cmy	10 STATE 11 ZIP CODE 12 TELEPHONE NUMBER				
Same as owner	Same as owner'				
13 TYPE OF OWNERSHIP (Check one)	Same as owner'				
■ A. PRIVATE □ B. FEDERAL:	☐ C. STATE ☐ D.COUNTY ☐ E. MUNICIPAL				
F. OTHER:	G. UNKNOWN				
(Specify)					
14 OWNER/OPERATOR NOTIFICATION ON FILE (Check all tinal apply) ■ A. RCRA 3001 DATE RECEIVED: 10 / 30 / 80 □ B. UNCONTROL	LED WASTE SITE (CERCLA 103 c) DATE RECEIVED: NO.NE				
MONTH DAY YEAR	MONTH DAY YEAR				
IV. CHARACTERIZATION OF POTENTIAL HAZARD					
I AMP VEC INDIE SENTING / TEL	A CONTRACTOR C. STATE D. OTHER CONTRACTOR				
I LING	Water Quality Journal (yearly since 1949)				
02 SITE STATUS (Check one) 03 YEARS OF OPER	RATION				
	1940'S present Dunknown BEGINNING YEAR ENDING YEAR				
04 DESCRIPTION OF SUBSTANCES POSSIBLY PRESENT, KNOWN, OR ALLEGED					
Sludges (toxic / persistant)					
bases (corrosive)					
heavy metals (toxic / persistant) OS DESCRIPTION OF POTENTIAL HAZARD TO ENVIRONMENT AND/OR POPULATION	,				
groundwater (population /environment) drinking water (population)					
drinking water (population)					
V. PRIORITY ASSESSMENT					
On PRIORITY FOR INSPECTION (Check one, if high or medium is checked, complete Pair 2 - Waste Into A. HIGH (Inspection required promptly) (Inspection required) (Inspection Image: Checked and Image: Ch	ormalion and Part 3 - Description of Hazaroous Conditions and Incidents) D. NONE a variable basis) (No further action needed, complete current disposition form)				
VI. INFORMATION AVAILABLE FROM					
01 CONTACT 02 OF (Agency/Organ.	D3 TELEPHONE NUMBER				
William J. Tischler Technical Director of Hoover's Die (ast Div. 1313) 429-9411 G4 PERSON RESPONSIBLE FOR ASSESSMENT OS AGENCY D6 ORGANIZATION D7 TELEPHONE NUMBER OB DATE					
04 PERSON RESPONSIBLE FOR ASSESSMENT 05 AGENCY	06 ORGANIZATION 07 TELEPHONE NUMBER 08 DATE ()				

SEPA

POTENTIAL HAZARDOUŞ WASTE SITE PRELIMINARY ASSESSMENT PART 2 - WASTE INFORMATION

I. IDENTIFICATION					
DI STATE	02 SITE NUMBER D980795512				

II WASTE ST	TATES OHANTITIES AN	ID CHARACTER		- INTONIATION			
□ A SOLID □ E. SLURRY must be		ITY AT SITE 03 WASTE CHA		CTERISTICS (Chock DE Indi apply) C			
			00 1.0			•	
III. WASTE T	SUBSTANCE N		Tax 00000	001007 05 115 10 105	00.00		
SLU	SLUDGE	AME	1	02 UNIT OF MEASURE		14.	- A.1
OLW	OILY WASTE		unk		INE Facili	ty operates	a meral
	SOLVENTS				casting as	nd electrople	ating
SOL					industry	that paints	and
	PESTICIDES	15,410,41.0	<u> </u>		assembles	nd electroph that paints components	for the
occ	OTHER ORGANIC CH				auto indu	istry.	
100	INORGANIC CHEMIC	ALS					
ACD	ACIDS						
BAS	BASES		unk				
MES	HEAVY METALS	·	1 unk				
	DUS SUBSTANCES (See A)		Í .	0.4.67.05.405.404.65	OCCU METHOD	T	06 ME ASURE OF
01 CATEGORY	02 SUBSTANCE N	AME	03 CAS NUMBER	04 STORAGE/DISF	OSAL METHOD	05 CONCENTRATION	CONCENTRATION
			-				
							-
						· .	
V EEEDSTO	CKS (See Appendix for CAS Numbe	· · · · · · · · · · · · · · · · · · ·	1	L		1	·
			02 CAS NUMBER	CATECORY	01 EEEDSY	OCK NAME	02.045.444.055
CATEGORY	01 FEEDSTOC	KIANIL	02 CAS NUMBER	CATEGORY	01 FEEDSTO	JONNAME	02 CAS NUMBER
FDS				FDS			
FDS				FDS .			
FDS				FDS			
FDS				FDS			
VI. SOURCES	S OF INFORMATION ICAE	specific references, e.g.,	state files, sample analysis.	reports)			
	d Environment water records						

SEPA

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT

I. IDENTIFICATION					
O1 STATE	02 SITE NUMBER 0980795512				

PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

IL HAZADDOUG CONDITIONS AND INCIDENTS			
II. HAZARDOUS CONDITIONS AND INCIDENTS 01 A GROUNDWATER CONTAMINATION	02 DOBSERVED (DATE:) POTENTIAL	□ ALLEGED
03 POPULATION POTENTIALLY AFFECTED:	04 NARRATIVE DESCRIPTION		
water quality personel indicate his	sh readings for heavy m	etals and sus	spended
Solid in yearly twenty-four hour			
01 B. SURFACE WATER CONTAMINATION 03 POPULATION POTENTIALLY AFFECTED: 195	02 □ OBSERVED (DATE:	_) III POTENTIAL	□ ALLEGED
Years ago, any runoff went into ditches	and then into the Sal	ine River.	
Potential source of contamination duri	ng periods of high runot		
01 D C. CONTAMINATION OF AIR	02 D OBSERVED (DATE:) D POTENTIAL	□ ALLEGED
03 POPULATION POTENTIALLY AFFECTED:	04 NARRATIVE DESCRIPTION -		: ::
01 ☐ D. FIRE/EXPLOSIVE CONDITIONS 03 POPULATION POTENTIALLY AFFECTED:	02 □ OBSERVED (DATE: 04 NARRATIVE DESCRIPTION	_) □ POTENTIAL	□ ALLEGED
_			•
·			: -
01 DE. DIRECT CONTACT 03 POPULATION POTENTIALLY AFFECTED:	02 OBSERVED (DATE: D4 NARRATIVE DESCRIPTION	_) DOTENTIAL	□ ALLEGED
·			
01 T. CONTAMINATION OF SOIL 03 AREA POTENTIALLY AFFECTED:	02 OBSERVED (DATE: L969 04 NARRATIVE DESCRIPTION	POTENTIAL	□ ALLEGED
When the area flooded in 1969, water	levels reached 10'-15'	above the river	on the
north side. Photographs indicate a hol			
plant, but it no longer exists and the ex	act location is unknown	, Site Size: 600'	x 1100'
01 @ G. DRINKING WATER CONTAMINATION	02 M OBSERVED (DATE: 6~19~80 04 NARRATIVE DESCRIPTION		
Technical Virector Tischler stated that	after high ammonia conce	ntrations were t	found in his
observation wells, he independently to	ested well water and Sal	line City water	r in areq
homes and also found high values.		•	
01 D H. WORKER EXPOSURE/INJURY 03 WORKERS POTENTIALLY AFFECTED:	02 □ OBSERVED (DATE: 04 NARRATIVE DESCRIPTION	_) DOTENTIAL	□ ALLEGED
· ·	•	-	
,	-		
01 🗆 I. POPULATION EXPOSURE/INJURY 03 POPULATION POTENTIALLY AFFECTED:	02 □ OBSERVED (DATE: 04 NARRATIVE DESCRIPTION	.) D POTENTIAL	□ ALLEGED
I ·			

POTENTIAL HAZARDOUS WASTE SITE

I. IDENTIFICATION

	ELIMINARY ASSESSMENT I OF HAZARDOUS CONDITIONS AND INCIDENT:	S MILDO	180795512
II. HAZARDOUS CONDITIONS AND INCIDENTS (Contin			
01 D J DAMAGE TO FLORA 04 NARRATIVE DESCRIPTION	02 OBSERVED (DATE:)	□ POTENTIAL	□ ALLEGED
of the damage to fauna of narrative description (include name(s) of species) fish kills in past not linked wit	02 DOBSERVED (DATE:) th Itoover Universal.	☐ POTENTIAL	■ ALLEGED
01 □ L. CONTAMINATION OF FOOD CHAIN 04 NARRATIVE DESCRIPTION	02 OBSERVED (DATE:)	□ POTENTIAL	□ ALLEGED
01 M. UNSTABLE CONTAINMENT OF WASTES (Spills/runoff/standing liquids/leaking drums) 03 POPULATION POTENTIALLY AFFECTED: 195	02 OBSERVED (DATE:) 04 NARRATIVE DESCRIPTION	POTENTIAL	□ ALLEGED
Effluent discharged to unlined lago Lagoon sludge Susceptible to runo			
01 □ N. DAMAGE TO OFFSITE PROPERTY 04 NARRATIVE DESCRIPTION	02 OBSERVED (DATE:)	□ POTENTIAL	□ ALLEGED
01 □ O. CONTAMINATION OF SEWERS, STORM DRAINS, 04 NARRATIVE DESCRIPTION		☐ POTENTIAL	□ ALLEGED
(
01 □ P. ILLEGAL/UNAUTHORIZED DUMPING 04 NARRATIVE DESCRIPTION	02 OBSERVED (DATE:)	POTENTIAL	☐ ALLEGED
05 DESCRIPTION OF ANY OTHER KNOWN, POTENTIAL, (OR ALLEGED HAZARDS		
III. TOTAL POPULATION POTENTIALLY AFFECTED:	195		
IV. COMMENTS			
Continued monitoring of lagoons	for heavy metals discharge.		
V. SOURCES OF INFORMATION (Cite specific references, e. g.	state files, sample analysis, reports)		
Ecology & Environment FIT files,	Region I - Chicago		·
MDNR water records and report	ts		